



American Competitiveness Institute

Mechanical Shock, Humidity, Salt Fog And Lead Residue Testing September 21, 2004





- Salt Atmosphere Testing Status
- Humidity Testing Status
- Mechanical Shock / Vibration Testing Status
- Lead Residue Testing Status





acı







- Salt Atmosphere Test Status

- Salt Atmosphere Testing Performed September, 2004
 - Based on ASTM B117 Test Method for 48 hours
 - SnPb Boards: Serial Numbers 35, 36, 37
 - SnAqCu Boards: Serial Numbers 104, 105, 106
 - SnAgCuBi Boards: Serial Numbers 143, 144, 145

All Passed Salt Atmosphere Testing

- Checked continuity on specific packages
- Found some failures prior to the test
- Found no failures after test
- Report to be generated



aci





- Temperature Humidity Test Status

- Temperature Humidity Testing Being Scheduled
 - Based on MIL-STD 810F; Test Method 507.4
 - SnPb Boards: Serial Numbers 38, 39, 40
 - SnAgCu Boards: Serial Numbers 107, 108, 109
 - SnAgCuBi Boards: Serial Numbers 146, 147, 148
- Will Check Continuity Prior To Testing





acı









- Test Procedure Approved
 - Tooling being designed and manufactured
 - Anatech System being ordered
- All Boards Received
- Pathfinder Boards Identified
 - SnPb Boards: Serial Numbers 25, 61
 - Used to set-up test fixtures at BAE Systems
- Testing being scheduled with BAE Systems
 - Will notify team when tests will be performed



aG





Mechanical Shock, Humidity, Salt Fog And Lead Residue Testing aci **Test Boards Test Boards Test Fixture**



Mechanical Shock, Humidity, Salt Fog And Lead Residue Testing

- Mechanical Shock / Vibration Test Status

- Mechanical Shock Test Set 1
 - MIL-STD 810F; Method 516.5; Procedure 1
- Boards Identified
 - SnPb Boards: Serial Numbers 26, 27, 62, 63
 - SnAgCu Boards: Serial Numbers 95, 96, 151, 168
 - SnAgCuBi Boards: Serial Numbers 134, 135, 196, 197



Mechanical Shock, Humidity, Salt Fog And Lead Residue Testing

- Mechanical Shock / Vibration Test Status

- Mechanical Shock Test Set 2
 - Modified version of MIL-STD 810F; Method 516.5; Procedure 1
 - Hardware will be tested to failure
- Boards Identified
 - SnPb Boards: Serial Numbers 28, 29, 64, 65
 - SnAgCu Boards: Serial Numbers 97, 98, 170, 171
 - SnAgCuBi Boards: Serial Numbers 136, 137, 198, 199




- Lead Residue Test Status

Metallurgy Analysis


- Microsectioning
- Determine what intermetallics are in Lead Free solder joints
- Require direction and funding

Examples of Lead Free Intermetallics

- ACI Lockheed Martin Lead Free Solder Rapid Response Project
- Hardware experienced 126 thermal cycles; -55°C to 125°C



Unstressed Solder Joint



Stressed Solder Joint



aci















Mechanical Shock, Humidity, Salt Fog And Lead Residue Testing


- Lead Residue Test Status




Unstressed Component Interface



Unstressed Pad Interface



Stressed Component Interface



Stressed Pad Interface